

# Verspanings parameters

## Cutting Data

Mat.	ØD	Vc M/min	Z	fz mm	ap mm	ae mm	
<b>P1.1</b>	3.0	220	5	0.015	3	3	
	4.0	220	5	0.020	4	4	
	5.0	220	5	0.030	5	5	
	6.0	220	5	0.030	6	6	
	8.0	220	5	0.040	8	8	
	10.0	220	5	0.065	10	10	
	12.0	220	5	0.070	12	12	
	16.0	220	5	0.090	16	16	
	20.0	220	5	0.110	20	20	
<b>Steel</b> < 800N/mm <sup>2</sup>	25.0	220	5	0.150	25	25	
	<b>P2.2</b>	3.0	150	5	0.010	3	3
		4.0	150	5	0.015	4	4
		5.0	150	5	0.020	5	5
		6.0	150	5	0.025	6	6
		8.0	150	5	0.030	8	8
		10.0	150	5	0.050	10	10
		12.0	150	5	0.060	12	12
		16.0	150	5	0.070	16	16
20.0		150	5	0.080	20	20	
<b>Heat Treatable steel</b> < 1100N/mm <sup>2</sup>	25.0	150	5	0.090	25	25	
	<b>P3.2</b>	3.0	70	5	0.010	3	3
		4.0	70	5	0.020	4	4
		5.0	70	5	0.025	5	5
		6.0	70	5	0.030	6	6
		8.0	70	5	0.040	8	8
		10.0	70	5	0.060	10	10
		12.0	70	5	0.070	12	12
		16.0	70	5	0.085	16	16
20.0		70	5	0.100	20	20	
<b>High Alloy steels</b> < 1600N/mm <sup>2</sup>	25.0	70	5	0.120	25	25	
	<b>P4.2</b>	3.0	80	5	0.010	3	3
		4.0	80	5	0.015	4	4
		5.0	80	5	0.020	5	5
		6.0	80	5	0.025	6	6
		8.0	80	5	0.030	8	8
		10.0	80	5	0.050	10	10
		12.0	80	5	0.060	12	12
		16.0	80	5	0.065	16	16
20.0		80	5	0.085	20	20	
<b>Cold working tool steel</b> 12% Chrom	25.0	80	5	0.095	25	25	
	<b>M2.1</b>	3.0	120	5	0.008	3	3
		4.0	120	5	0.010	4	4
		5.0	120	5	0.015	5	5
		6.0	120	5	0.020	6	6
		8.0	120	5	0.025	8	8
		10.0	120	5	0.030	10	10
		12.0	120	5	0.040	12	12
		16.0	120	5	0.050	16	16
20.0		120	5	0.070	20	20	
<b>Stainless steel</b> Austenitic 303-304-316	25.0	120	5	0.100	25	25	
	<b>K1.2</b>	3.0	180	5	0.015	3	3
		4.0	180	5	0.020	4	4
		5.0	180	5	0.025	5	5
		6.0	180	5	0.030	6	6
		8.0	180	5	0.050	8	8
		10.0	180	5	0.070	10	10
		12.0	180	5	0.080	12	12
		16.0	180	5	0.090	16	16
20.0		180	5	0.100	20	20	
<b>Cast iron</b>	25.0	180	5	0.150	25	25	

### Correctie Correction

Ae	Ap	Vc	fz
Ae= <0,4xD	1xD	20%	20%
Ae= <0,4xD	1,5xD	10%	10%
Ae= <0,05xD	2xD	20%	100%



**Contour** Ap<1,5xD  
en Ae<0,5xD



**Finish** Ap<2xD  
en Ae 0,05xD